

W1127-0132

5c.1227. H.

2

20 AUG 1930

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel Sc.Sr. "MAKAMBO". Report Lon. No. 95413a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/32.)

2nd No. 3 SURVEY PARTLY HELD.

When due 9.30 When proposed to be completed _____

Portion of Survey held, &c., _____

The 2nd S.S. No.3, due 9.30, has been partly held.

Repairs to reverse frames in fore peak and to collision bulkhead require to be completed and examined.

The Owners now forward a letter stating that they have decided not to proceed with the reclassification.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class.

Insert ...

19.8.30. 2020
Lloyd's Register Foundation