

It is submitted the New York Surveyors should be requested to state whether the screw shaft of this vessel is fitted with a continuous liner and, if not, whether the joints have been burned as required by the Rules.

These particulars are not stated in the report.



2020

Lloyd's Register
Foundation
W1128-0303