

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME STEEL S.S. "COTATI"

Report S.Fo.

No. 3142

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.) — Extract from Sub-Committee's Report, 24/6/22.

Nature of Survey

When due

The Downston Pump has been dispensed with for the present.

100 A.1. (steel) "Shelter Dk. with freeboard."

1 Dk. (steel) and Shelter Dk (steel) and Webframes.

Longitudinal Framing"


Cell DB 348' 1351 t. MT 30' 554 t. FPT 75t. APT 48t.

FR. 4 BH to Shelter Dk. 3 BH to Upper Dk. pt. cems.

A.C.P.

P 34', F 39' on Shelter Dk.

The Surveyors should be requested to state clearly how many bulkheads are stiffened as required by the rules, for bulkheads with respect to Shelter Deck, for record in Register, as the number given in report does not agree with the plans.



Lloyd's Register
Foundation

W1130-0075

Noted for posting