

W1131-0114

f Surveyors _____

Received from Chief Surveyors _____

NAME STEEL S.S. "CLAIRTON" Report N.Yk. No. 17064,

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Survey _____

When due _____

The Downton Pump has been dispensed with for the present.

* 100 A.1. (steel) "Shelter Deck with Freeboard" Carrying Oil Fuel in Double Bottom
and Peaks. F.P. exceeding 150°F

1 Deck (steel) and Shelter Dk (steel) and Webframes. Longitudinal Framing.

Cell DA 331' 1512t. FPT 137t. APT 175t.

FK. 7 BH to Shelter Dk. pt. conn. A.&C.P. P45', B110', F38' on Shelter Deck

The Surveyors should be requested to state whether it is intended
y Oil Fuel as cargo in Double Bottom & Peaks.

yes see above

© 2020
Lloyd's Register
Foundation

26.8.19