

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 20 March 35 When handed in at Local Office 20/3/35 Port of NEWCASTLE-ON-TYNE

No. in Reg. Book. Survey held at Wallsend on Tyne Date, First Survey 27 Feb Last Survey 16 March 1935
91068 on the Wood, Iron or Steel S.S. ROXBURGH (No. of Visits 7)TONNAGE:— Built at Bunkisland By whom Bunkisland S.B.C. When 1935 3
GROSS Owners B. J. Sutherland & Co. Ltd. Owners' Address
UNDER DEK. Managers Port belonging to Newcastle
NETSurveyed Afloat or in Dry Dock? Afloat Name of Dock N.E. Marine Quay Destined Voyage
WB=CellDBorDBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Completion of First Entry (See Letter of 18 Feb. 1935 and London letter of 26 Feb. 1935).
Now doneThe Steering gear and windlass have been tested under working conditions and found satisfactory.
The Casings in way of the machinery & boiler spaces have also been completed.

SUMMARY OF DAMAGE REPAIRS:—

	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on felt). When put on, Month Year.
Caulking of Decks	State if Tanks now tested	Plating under Sounding Pipes	Boats
Coamings	Bulkheads	Engine Room Skylights	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Condition, how ascertained (State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Oil Bunkers	Sails
" " in way of sidelights	Rudder	Scuppers	Equipment letter
Breasthooks	Steering gear and its connections	Cargo Hatchways	Anchors, No. of
Transoms	Windlass	Hatches	Chain Locker
Frames	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Cables (State if now ranged)
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	" length mean diam. (on board)
Longitudinals	Have Watertight Doors now been examined and found efficient?	Treenails ditto	" Rule length size
Transverses		Breasthooks & Stemson ditto	Hawser & Warps
Floors		Transoms Pointers, & Crutches ditto	Standing and Running Rigging
Keelsons		Timbers of Frame at openings ditto	
Stringers		Ditto Ditto at other places ditto	
Inner Bottom Plating	Have Ventilators and their Coamings been examined and found efficient?	Stringers, Clamps & Shells ditto	
		Salting ditto	
		(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptn24, &c."

As far as now seen this vessel is eligible, in my opinion, for the Class Contemplated with record of build 3.35.

Survey Fee (per Section 20)	£	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	19
Travelling Expenses (if chargeable)	£	Received by me,
Second Surveyor's Fee (if any)	£	19

Committee's Minute

FRI. 5 APR 1935

Character Assigned

see J.E.R.p.h.

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

W1131-0160