

"GULFPENN"

N.Yk 41811

27 JAN 1942

N.Yk. S.O. 2-2-42.

The Surveyors should be informed it appears that to complete the Special Survey the after peak tank requires to be examined and the chain cables ranged and examined, and as the chain cables have not been ranged that the chain locker also requires to be examined. Further, that the freeboard as reported is incorrect. The rigging report is not attached as stated.

The Surveyors should be requested for their remarks.

the certificate
~~Submitted - Confirmation of the assignment of the notation of Special Survey should be withheld pending the Surveyors' reply.~~

MAB
23-1-42
[Signature]



© 2020

Lloyd's Register
Foundation

W1133-0006

Repairs A number of leaking shell rivets renewed. One hatch crawling & 3 covers renewed. Minor repairs

ION (whi
Book &
(Incl
+ L
B
CL
Fite
8.2
um
d) as
rified
2
AP
ed
dau
& l
d &
the
of t
comp
ra