

WOKINGHAM COPY.

Crank shaft journals still require to be examined  
Surveyor regrets these omissions from his report.

Your suggestion that the machinery should be LMC 6,41  
noted and agreed to.




© 2020

Lloyd's Register  
Foundation

W1133-0007

MOKISHAM COPY



© 2020  
Lloyd's Register  
Foundation

Noted.  
12.5.42  
Certificate to be issued until  
shifts finished  
cleared