

39

38

*Received from Chief Ship Surveyor*

" PELTON "

Rpt.

Hul. No.

50186

igned) as  
verified

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

The Hull Surveyors report a length of chain cable supplied to replace damaged length.

It is submitted the vessel appears worthy to remain as classed without record of survey.

In S.R.L. Structure in way of ESD. to be examined when device is removed.

18. 8. 39  
 18. 8. 39

to be examined when

© 2019

Lloyd's Register  
Foundation

M. of Wo  
sen Pitt.  
t on, Mont

s, &c. ....

w ascerta