

...liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water and  
...liners are fitted is the shaft lapped or protected between the liners

ANGITANE.

GLS. 49810

It is submitted that

vessel is eligible for

RECORD.

+ LMC 11.29.

OIL ENGINES. 2 AC 1a.

10cy. 357/16-63 NTP 2186

2DB. 100H. CL.

1 Crown & Co. Ltd. Gls.

*[Signature]*



© 2019

Lloyd's Register  
Foundation

...pipes pass through the vickers

...pipes pass through the deep tanks. None.

Have they been tested as per Rule

...Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times

Yes