

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19

When handed in at Local Office 19

Port of ReykjavikNo. in
Reg. Book.

Survey held at

Date, First Survey

Last Survey

2-4-1914

(No. of Visits)

20718

on the Wood, Iron or Steel

SS. "BRITISH WORKMAN"

TONNAGE :-

Built at

Belfast

By whom

Workman Clark & Co Ltd

YEAR.

MONTH.

1922

4

GROSS

6994

Owners

British Tanker Co Ltd

Owners' Address

(If not already recorded in Appendix to Register Book).

UNDER DK.

6533

Managers

Port belonging to

London

NET

4066

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

Cell D Bor DBa

feet ; uE & B

feet ; f

feet

total capacity

tons. FPT

tons ; APT

tons ; MT

feet

tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No.

4174

Port

GalParticulars of Classification (which must be inserted
precisely as in Register Book & Supplements)CHARACTER.
* for Special Survey.
Date of last Survey and of
Periodical Surveys.Machinery and Boiler
Surveys
(Including date of N.B., if any)

+100 A1

+6mc ms.

10.41

10.37

ss Shl No 3 5-34

BS. 10.40

" Bkn No 1-38

Og. 9.40

Carrying petroleum in bulk
Filled for oil fuel 4.22 etc

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as
painted on Ship and now verified

ft.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-

Shell Plates.

Frames.

R. Frames.

Floors and
Bracket Floors

Beams.

Inner Bottom
Plates.

Dk. Plates.

Other Items :-

Renewed ...

Removed and Fairred or Repaired

Fairred or Repaired in place ...

PRESENT CONDITION OF THE

Decks

Caulking of Decks

Coamings

Beams & Fastenings

Outside Plating

" " in way of sidelights

Frames

Reverse Frames

Longitudinals

Transverses

Floors

Keelsons

Stringers

Inner Bottom Plating

Have the Tanks been examined Internally?

Have the Tanks been tested?

Bulkheads

Ceiling

Cement or Asphalt

Rudder

Steering gear and its connections

Windlass

Have pumps been examined and found efficient?

Have Sluice Valves been examined and found efficient?

Have Watertight Doors been examined and found efficient?

Have Ventilators and their Coamings been examined and found efficient?

Air and Sounding Pipes

Doubling Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Openings, Covers, &c.

Oil Bunkers

Scuppers

Cargo Hatchways

Hatches

Planking

Caulking

Treenails

Breasthooks & Stemson

Transoms, Pointers & Crutches

Timbers of Frame at openings

" " at other places

Stringers, Clamps & Shelves

Salting

(State if examined.)

Copper, or Y.M.

(State if on Felt.)

When fitted, Month

Year

Boats

Masts, Yards, &c.

Condition, how ascertained
(State if wedges removed.)

Equipment letter

Anchors, No. of

Cables (State if now ranged)

" length mean diamr.

(on board.)

" Rule length size

Chain Locker

Hawsers & Warps

Standing and Running Rigging

Sails

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29) £ : :

Fees applied for,

Special Damage or Repair Fee (if any)
(per Sec. 29) £ : :

Received by me,

Travelling Expenses (if chargeable) £ : :


19

Second Surveyor's Fee (if any) £ : :

Committee's Minute

Character Assigned

Surveyor to Lloyd's Register of Shipping.



© 2020

Lloyd's Register
Foundation