

3m,11,39.

13 MAY 1940

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME "THE EMPEROR" Rpt. Sws. No. 22391

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/32.*)

The Swansea Surveyors report the vessel afloat and on account of damage through collision the forecastle side plating and framing in way found buckled and fractured. Temporary repairs have been effected.

The Surveyors recommend the indented forecastle sheer plating and strakes below (s.s.) and frames in way be dealt with at the first convenient opportunity.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended.

As Now, subject, etc.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.



© 2020

Lloyd's Register
Foundation

W1142-0035

10.5.40