

Managers Bow Harris  
(Where necessary to be entered in Reg. Book.)

5m.2.15

1

Sent to Chief Surveyors 6. 11. 18

*Received from Chief Surveyors*

VESSEL'S NAME

Shel S. S. Virgilina

## Report

Erk

No. 17377

For the **CHIEF SHIP SURVEYOR** and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24.5.1952*)

### Nature of Survey

When due

\* 100 A. 1. (Steel)

2 15% (Steel)

Cell D.B 360' 11816. D.T. a 36' 11096. A.P.T. 316

F.K. One intermediate BH & one lower d/b BH dispensed with

5 BH to upper. On 1 BH to 2<sup>nd</sup> only.

Am. Lycop. v. p. P 38 B 123 F 43

Carrying at full F.P. above  $150^{\circ}\text{F}$  w. A.B. = 0.7

Lloyd's Register  
Foundation

Angles on upper edge  
Spacing  
BEAMS. Poop Deck, Angle, Bulb Angle, Plate,  
Toe Bulb, or Channel  
Angles on upper edge

9½	3½	50	9½	3½	50
9	3½	48	8	3	48

Deck. Material and thickness  
**Bridge Deck Stringer Plate**, br'dth & thicknes  
Angle on ditto