

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 9.3.1942 When handed in at Local Office 9.3.1942 Port of Hull

No. in Reg. Book Survey held at Hull Date, First Survey Last Survey 19

4685 on the Wood, Iron or Steel M.V. "ATHELBERN" Built at ... By whom ... When 1911
GROSS 8780 Owners ... Owners' Address ...
UNDER DK 1150 Managers ... Port belonging to ...
NET 5145

Surveyed a float or in Dry Dock? Spec. Name of Dock King George Dock Destined Voyage
Cell DB or DBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
Last Report, No. 51521 Port Hull

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)
CHARACTER: * For Special Survey Date of last Survey and of Periodical Surveys.
Machinery and Hull Survey (including date of S.R., if any).

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined
Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Equipment

The Certificate covering the new lower anchors of the 2 1/2" Star line ...
The Certificate for the 30 lbs. of anchor cable also referred to ...
The Certificate above have been examined & have been returned to the Owners representative in Liverpool.

SUMMARY OF DAMAGE REPAIRS:—

	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Beams	Inner Bottom Plates	Dk. Plates	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter "A"
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	length mean diam. (on board)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting (State if examined.)	
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

For the information of the Committee.

Fees applied for, Received by me, 19

Survey Fee (per Section 20)	£
Special Damage or Repair Fee (if any) (per Sec. 20)	£
Travelling Expenses (if chargeable)	£
Second Surveyor's Fee (if any)	£

Committee's Minutes WED. 8 APR 1942
Character Assigned as now Subject



W1171-0141

