

The draught is 6" less than that corresponding to the ...

It is a question whether the full certificate  
should be issued pending the fitting of  
cement under the Boilers, which was omitted  
through an oversight by the Builders  
(See reply to inquiry  
- attached)

J. H. W.  
27.7.12.

Lloyd's Register  
Foundation

W1173-0058

Boiler and further the remaining specifications as shown on the accompanying