

ELECTRICAL INSTALLATION.

The Electrical Installation was found to be in need of extensive overhaul and repair. Work was commenced on part-rewiring of the starboard cabin midships - but was suspended.

W.B.

As due 5x2 part held
2 1/2 p3 due 5x2 part held 9.4.2
advised.

Repair held
The Res. equipment to the Auxiliary
Condenser are in need of
repair.

The vessel has been referred to the
Special Service & the
Cannys and repairs may
not be completed.

Submitted for the
consideration of
the Committee

12/4/44



© 2020

Lloyd's Register
Foundation