

REPAIRS, OR

Vessel placed in dry dock, shell plating & hulls cleaned & painted

2m.10.38.

1

V.S. held on shell

21 SEP 1939

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

SHROPSHIRE

Report

low

No. 113115

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey


Condition

When due

Subject to undented plating starboard side forward & port side being dealt with at the first convenient opportunity

af  
16.9.39

The vessel has now been taken over by the Admiralty (see Rpt 9)



© 2021

Lloyd's Register Foundation

W1175-0167

(State if examined.)

Standing and Running Ri

Under Survey & Testing

and found efficient

Class

Recommendation, &c.:—