

TONNAGE:-
GROSS 4876
UNDER DK. 4344
NET 2776

Built at Haverton Hill-on-Tyne By whom Furness S.B. Co. Ltd.
Owners Elmina Ltd.
Managers
Afloat at NE. M. quay
Middle Dock

When 1938 2

Owners' Address
(if not already recorded in Appendix to Register Book).
Port belonging to Freetown

Surveyed Afloat or in Dry Dock? ☒ Afloat ☐ in Dry Dock Name of Dock Destined Voyage

WB=Cell DBordBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

(Periodical Surveys, when held, must be reported in detail and notation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarized in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of First Entry (See H'bro Letter of 18 Jan. 38 & London Letter of 31 Jan. 38).
Now done.

The Engine and Boiler casings have been Completed Satisfactorily.
The Steam Windlass, the Steam Steering gear and auxiliary Steering gear have been tested under working conditions and found Satisfactory.
The vessel has also been placed in drydock & the bottom cleaned, examined and recoated.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year
Caulking of Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	Boats
Coamings	Bulkheads	Engine Room Skylights	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Coal Bunkers, Openings, Lids, &c.	Condition, how ascertained (State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Oil Bunkers	Sails
in way of sidelights	Rudder	Scupperns	Equipment letter
Breasthooks	Steering gear and its connections	Cargo Hatchways	Anchors, No. of
Transoms	Windlass	Hatches	Chain Locker
Frames	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Cables (State if now ranged)
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	length mean diamr. (on board)
Longitudinals	Have Watertight Doors now been examined and found efficient?	Treenails ditto	Rule length size
Transverses		Breasthooks & Stemson ditto	Hawser & Warps
Floors		Transoms Pointers, & Crutches ditto	Standing and Running Rigging
Keelsons		Timbers of Frame at openings ditto	
Stringers		Ditto Ditto at other places ditto	
Inner Bottom Plating	Have Ventilators and their Coamings been examined and found efficient?	Stringers, Clamps & Shells ditto	
		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

This vessel is eligible, in our opinion, for the Class Contemplated with record of Build 2.38.

Survey Fee (per Section 20) £ : : Fees applied for, 19
Special Damage or Repair Fee (if any) (per Sec. 20) £ : : Received by me, 19
Travelling Expenses (if chargeable) £ : :
Second Surveyor's Fee (if any) £ : :
A.E. Akester John A. Rowson
Surveyor to Lloyd's Register of Shipping.