

Decks, hatch coamings, beams battening down arrangements,

3.43.

124 AUG 1943

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "FORT McLEOD" REPORT Lon. No. 111308

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to (a bower anchor and 45 fathoms of chain cable being supplied and 2 bower anchors and stream anchor on board being submitted to Statutory Test), also permanent repairs being effected to bulwarks, stringer plate and sheerstrake etc. (s.s.) abreast fiddley at the Owners' convenience.

The LONDON Surveyors report the vessel placed in dry dock, bottom coated and minor repairs effected.

It is submitted the vessel is eligible to remain as classed with record of survey 7.43 subject as above.

As now, subject.
7.43 Lon.



© 2020

Lloyd's Register
Foundation

W1188-0144