

.38
.38

San Delfino

Nov. 96422.

It is submitted that before this
case receives consideration the Surveyors
should be requested to verify the
internal diameter of the donkey boiler.
According to the plan it is $12' - 3\frac{15}{16}"$.



© 2019
11/7/38.

Lloyd's Register
Foundation

Are they fixed sufficiently high on the ship's side to be seen without lifting the platform plates ✓ Are the Overboard Discharges above or below
Are they each fitted with a Discharge Valve always accessible on the plating of the vessel ✓ Are the Blow Off Cocks fitted with a spigot and