

37. 25

Received from Chief Ship Surveyor

No. 4888.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Cladding Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/92.)

1<sup>st</sup> Entry

R.A.

Dr. Amos.  
29. 7. 11.

*28/7/11*

© 2020

Lloyd's Register  
Foundation

Spacing	16%	26%
EAMS, Upper Deck, Single Angle, Bulb Angle	7 3 .38	7 3 .38

„ Tie Plates, outside Hatchways .....

„ Deck, \* Material and thickness *Steel*

**Third, Fourth & Fifth Deck Stringer Plate,**  
*IN HOLD No 1* breadth and thickness