

(2m, 11.8. - H.)

1

Sent to Chief Surveyors 14. 12. 08

Received from Chief Surveyors

VESSEL'S NAME

S.S. *Linga*

Report

*Rom*

No.

1362

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(2m, 11.8. - H.)

1

Sent to Chief Surveyors

30. 1. 09

Received from Chief Surveyors

VESSEL'S NAME

S.S. *Linga*

Report

*Rom*

No.

1362

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." — Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due


It is submitted the Bombay Surveyor  
be advised.

*JRR*  
1. 2. 09

*C. J. J.*  
1/2/09

For M. L. Astill  
broke down *Rom* 2/2/09

*J. H.*  
1. 2. 09



© 2020

Lloyd's Register  
Foundation  
W1206-0134

inside plating. This vessel was examined by the Surveyor in

dry dock in January 1907 when she was three years old and some