

main breach to outside of plank ...  
Depth in hold from tonnage deck to ceiling at midships ...

15 6.5

9500,12,10

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Steel SS. "JAUNTY" Report Gls. No. 39816

**For the CHIEF SHIP SURVEYOR**

(In cases which have to be submitted to the Clasing Committee "the endorsement to contain a succinet summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Clasing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey \_\_\_\_\_

When due \_\_\_\_\_

⊗ A. 1. (steel) "For Towing Purposes."  
1 Dk (steel)

Cell DB u cross bunker 14' 15t. f 18' 10t.

FPT 15t. APT 35t.

FK. 5 BH. Com. Lloyds A&C.P.

B 4 F 93'

Date of Build 3.20



© 2021

Lloyd's Register Foundation

6210-609M

ways

4.10

Cubic Metres

Masters Accommodation  
Boatswain's Store Room 6.10

23.05