

By Chief Ship Surveyor 1. 1. 02

Received from Chief Ship Surveyor

EL'S NAME *St. S. S. "Korana"* Report *Sld.* No. *20794*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/02.)

of Survey *First entry.*

It is submitted that before this case receives the consideration of the Committee the first entry report and approved sketch of midship section should be returned to the Surveyors and it should be pointed out to them that the number of ^astrikes of plating in the report ^adoes not agree with the midship section, and they should be requested to rectify the same. It should at the same time be pointed out to them that the moulded depth of spar deck vessels is required to be taken at the main deck for record on the Register in Book, and they should state this on the report; and further the record of decks of spar deck vessels three tiers of beams have to be accounted for, and the record as it should appear in the Register Book in this case is LDK (Stl) & Spar Dk (Stl) 3 tr B, ^{and it} which should have been stated thus in their report.

Fr. to Sld. 1/1/02

C.H.P.
1/1/02



© 2020

Lloyd's Register
Foundation

W1217-0190

Quarter, 'tween Dks., " " in-Hold " "

TWO COMPLETE SONS

Forecastle Deck Stringer Plate, b'dth & th'kns

Angle on ditto Tie Plates PLATED UNDER WINDLASS

31 3 1/2 x 3 1/2 13