

Ship Surveyor

ME

20/10/11

At St No 91

Received from Chief Ship Surveyor

Rpt.

Not

No.

24311  
7249

Reports of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.

First entry

It is submitted that action on these reports  
delayed until the subboards, which are a  
condition of the vessel's classification, are  
fully marked on the vessel's side. Verified  
the Society's Surveyors.

W 20/10/11

The Hull Surveyors should be informed that it is  
required that the angles forming the boiler seating  
are fully riveted as required but they should state if  
it is so.

The Hull Surveyors should be informed  
full 20/10/11



© 2020

Lloyd's Register  
Foundation

W1281-0144