

2/5. "Kian Gwan".

Rot 15761.

It is Submitted that the Rotterdam Surveyors should be informed it is concluded that the intermediate shafts of this vessel are fitted $9\frac{3}{4}$ " diameter as ~~per~~ approved & not $9\frac{1}{4}$ " as reported, also that the separate donkey section is fitted $3\frac{1}{2}$ " diameter & not 3" diameter as reported, but they should state if this is so.

Plant
Rot 3/11/26
RS Return

Report to
Rotterdam Surveyors
H. J.

W.D.
3/11/26

© 2020

Lloyd's Register
Foundation

- 1 Set of feed and bulge pump valves
- 1 set of springs for the H.P. and M.P. cylinder