

DIMENSIONS.

FEET.

Length

Framing Depth "d," at middle of length. See }  
Sec. 3 (1d) ..... }  
Proportions—Depth to Length—Uppermost con- }  
tinuous deck to top of keel ..... }

8-33

Residence *PASEO COLON 195*  
*BUENOS AIRES,*

Port of Registry *BUENOS AIRES*

5c.12.25.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *SA S PATO REAL*

Rpt. *Sou*

No. *13311*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

*1. Long*  
Transverse No. *300*

Depth "d" ✓

Framing: Table No. ✓

Description *angle frames as approved*

*2* Longitudinal No. *995*

Proportions  $\frac{\text{Length}}{\text{Depth}} =$  *8.33*

Deck Sheerstrake *as approved*

*Revised Rule*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ *A* — (Steel). For towing services at Buenos Aires  
*1 D\* (Std).*  
*F.P.T. 1/2 t.*  
*F.K, 4 B.H., Cen.*



© 2020

Lloyd's Register Foundation

*W1233*

*0179*

Bracket Floors, breadth and thickness at }  
middle line..... }

" " breadth and thickness at }

Forecastle Deck, Angle, [ or [