

on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on

16 OCT 1931

s. s. "MEISEI MARU" London 96795a

Boiler Survey became due 4.31.

The Kobe Surveyors, in reply to enquiry state that the Owners have informed them they do not desire to continue the class in the Society's Register Book.

IT IS SUBMITTED the vessel's class be withdrawn from the Register Book, and three dots inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class.

Insert ...

 
16.10.31.



© 2020

Lloyd's Register Foundation

W1236-0156

Special Damage or Repair Fee (if any).....£

19
Received by me.

On 6.31.31
to write on