

Surveyors

Received from Chief Surveyors

NAME Steel S.S. "STEEL AGE" Report N. Yk. No. 18082

For the CHIEF SHIP SURVEYOR

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

When due

100 A.1. (steel) "Shelter Dk. with freeboard."

1 Dk (steel) & Shelter Dk. (steel) and Webframes. Longitudinal Framing.

Cell DB 331' 1512 t. FPT 187 t. APT 175 t.

FK. 6 BH. to Shelter Dk. pt. com. A & C.P. P45', B 110', F 38' on Shelter Dk.

M *AEB.*
31-3-20

It is concluded, the machine at which chain cables were tested, has been examined and reported upon, also that the hand fire pump fitted is of the muntion type, but the Surveyors should be requested to state if this is so.

9/0 3/5/2

W124-0056.1

Lloyd's Register
Foundation