

# REPORT of SURVEY for REPAIRS, &c.

Writing Report 20-2-28 When handed in at Local Office 19 Port of Rangoon  
Survey held at Rangoon Date, First Survey 11-11-27 Last Survey 21-2-1928  
(No. of Visits Six)

ONNAGE - Built at Paisley By whom Fleming & Ferguson Ltd. When  
SS 129.19 Owners The Burma Oil Co. Ltd. Owners' Address  
ER DK 109.83 Managers Port belonging to  
55.89

veyed Afloat or in Dry Dock? Name of Dock Destined Voyage  
= Cell DBor DBa feet; uE&B feet; f feet  
capacity tons; FPT tons; APT tons; MT feet tons.

S.B. - All alterations in the existing records should be underlined.  
the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides  
examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing,  
and of the inner bottom plating, especially in the boiler space.

Report, No. Port

ical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the  
of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs  
ount of Damage (the cause of which must be stated) should be separated from Repairs due to other causes;  
sides being detailed in the body of the report, should be summarised in the form shown below. Whenever the  
ement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on  
ck of this form. State also the dates and initials of any letters respecting this case.

age cases where the Surveyor has not made a special damage report he is required to state whether he  
red his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

RS, OR EXAMINATION AS PER RULE, FOR

This vessel has been re-erected and completed at this port to my satisfaction, the  
rkmanship being good. The deck, bulkheads and peaks were flooded or hose tested as  
quired by the Rules and found to be watertight. The inner surfaces of bottom plating  
e not protected with cement, but have been treated with three coats of paint at Owners  
request. Pumping arrangements when fitted were tested and found in order.  
e equipment, as detailed in First Entry Report No. 46813 from Glasgow, has been placed  
board and verified by me. As the anchor certificates, have not as yet come to hand,  
was unable to compare the markings on the anchors with those mentioned on the certifi-  
ates. Certificate numbers marked on the five anchors, however are as follows:-

L.P.H.N / L.P.H.N  
88955 / 88959

RY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

CONDITION OF THE	State if Tanks have been examined inside	Dblig. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
of Decks	State if Tanks now tested	Engine Room Skylights	(State if on Felt). When put on, Month Year
Fastenings	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Boats
Plating	Ceiling	Scuppers	Masts, Yards, &c.
Planks	Cement or Asphalt (State which.)	Cargo Hatchways	Condition, how ascertained (State if wedges removed)
Frames	Rudder	Hatches	Sails
Frames	Steering gear and its connections	Planking of Wood Vessels	Equipment letter
Frames	Windlass	Caulking ditto	Anchors, No. of
Frames	Have Pumps now been examined and found effi- cient?	Treenails ditto	Cables (State if now ranged) length size (on board) Rule length size
Frames	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Hawser & Warps
Frames	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Standing and Running Rigging
Frames	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	
Frames		Ditto ditto at other places ditto	
Frames		Stringers, Clamps & Shells ditto	
Frames		Salting ditto (State if examined.)	

eral Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon  
this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of  
survey 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

aking into consideration that the vessel has been re-erected and completed at this port  
to my satisfaction, and the Rules of the Society complied with, I recommend that she be  
lassed + A1 "Dredger" "For river and harbour service" in the Register Book.

ee (per Section 29)	Rs. 211/-	Fees applied for, 20-2-1928
Damage or Repair Fee (if any) (Sec. 29)	£	Received by me, 20-2-1928
Expenses (if chargeable)	£	
Surveyor's Fee (if any)	£	

Committee's Minute  
Character Assigned  
+ A1 Dredger  
For River & Harbour Services  
Subject  
+ L.M.C. 2:28. 09.  
TUES. 1 MAY 1928  
Surveyor to Lloyd's Register of Shipping  
R. P. Taylor  
3 APR 1928  
2020 Without  
As now spl. Cond.  
note filled for at full  
2:28.3P. above 100  
Wend



t. 9.

Repo

Date of writt

Date of writt

Date of writt

Date of writt

Date of writt

Date of writt

## Date of writt

Date of writt

Date of writt

## Date of writt

Date of writt