

13 OCT 1931

Chief Ship Surveyor _____
Received from Chief Ship Surveyor _____
NAME Steel Twin Sc. Sr. "GASCOYNE". Rpt. Fre. No. 469.

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.

Survey

The class is subject to indented bottom plating etc. being dealt with at the Owners' convenience.

The 2nd S.S. No.3, due 9.30, has been partly held and a proposal to complete same by 8th January 1932, has been agreed to.

Repairs are required to shell plating etc. /

The Fremantle Surveyor now reports the vessel to have lost a bower anchor and sixty fathoms of chain cable.

The Surveyor recommends the equipment be placed in order at the earliest opportunity.

The year of grace expired 9.31.

It is submitted action be deferred.



© 2020

Lloyd's Register
Foundation