

28 OCT 1931

Inspected by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel S.S. "MAGELLAN" Rpt. Ply. No. 6843

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/192).

Nature of Survey _____

The 2nd S.S. No.1, due 6.29, has been partly held and to complete same all Rule requirements remain to be carried out except the examination of the bottom and rudder in dry dock, ranging of chain cables, examination of anchors, chain locker, Nos. 2 and 4 holds and tween decks, forward cross bunker (shelter tween decks), internal examination of Nos. 3 and 7 double bottom tanks, lifting of ceiling and testing of Nos. 2, 3, 7 and 8 double bottom tanks.


The vessel has been laid up and the Owners have furnished the usual undertaking.

The Plymouth Surveyors now report the vessel examined afloat, the holds, bilges, engine and boiler spaces and main bunkers examined and found in satisfactory condition.

It is submitted action be deferred.

[Handwritten signature]

[Handwritten signature]
28.10.31



© 2020

Lloyd's Register Foundation

W1246-0036