

122 OCT 1932

Surveyor

Received from Chief Ship Surveyor

Steel S.S. "SCOTSCRAIG"

Rpt.

Sba.

No. 2924

the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

ment to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points in the endorsement."—*Extract from Sub-Committee's Report, 24/5/32.*

The 2nd S.S. No.1 became due 2.32 and a proposal to carry out within the year of grace has been agreed to.

Permanent repairs are required to the tank top under boilers.

The Sourabaya Surveyor now reports all cargo holds and tween examined and found in order for carrying a cargo of sugar.

It is submitted action be deferred.

*Engine Room tank to be scaled & cement worked
as per Colombo Report No 752*



© 2020

Lloyd's Register
Foundation

W1247-0284

ificate of Classification to
d "Cargo battens not
NSHELTER TWEEN DECKS
nd the same notation to be
the Register Book.