

SUNWOOD.

5c.12.18.

F.E.

Received by Chief Ship Surveyor 9.9.18

Received from Chief Ship Surveyor _____

VESSEL'S NAME Sheless War Beach Rpt. Rmc No. 71236

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 72

Depth "d" 20.7

Framing: Table No. 3

Description Bulk and a approx

Longitudinal No. 23832

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{10.03}{}$

Bridge Deck Sheerstrake as approved

The duntown pump & bridge anchor have been dispensed with as in Standard Vessels.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A.1. (Steel) as recd

100A (Steel)

Cell 5B 284' 724C F.P.T. 110 C. Q.P.T. 123C

FK. 7BH. pl. Cam. L. 100' 123' P 33' B 100' F 29'

The Certificate of Classification, to be endorsed "Curry battens not fitted," and the same notation to be printed in the Register Book.

[Signature]

3.9.18

W1250-0167



© 2020 Lloyd's Register Foundation