

30th July, 1926.

s/s. "Theydon"

Fal 6571

It is submitted the Falmouth Surveyors be requested to state whether the Screw Shaft is fitted with 2 liners or no liners, if the latter, they should state whether the stern bush is fitted with an outer oil gland.

2 Liners
See Fal. H.V. 6/9/26.

J.W.D.
3/8/26.
R

AWD

© 2020

Lloyd's Register
Foundation

W1251-a196