

Received from Chief Ship Surveyor

2 JUL 1932

Surveyor

Steel Sc. Sr. "DIONI"

Rpt. Bla. No. 1151

the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

... to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also ... out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points ... ed in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

The class is subject to the shifting beams and fore and afters between deck cargo hatchways being repaired at the first opportunity indented shell plate G3, port side, being dealt with at a favourable opportunity.

The 3rd S.S. No.1 became due 8.31 and a proposal to carry out within the year of grace has been agreed to.

The Braila Surveyor, who was authorized, now reports the vessel examined afloat, the requirements of the special survey partly complied and minor repairs carried out.

Repairs are required to wasted tank top plating under the covers.

It is submitted action be deferred.

To complete the Survey + repairs - See Report.

Certificate of Classification to ... Cargo buttons not ... and the same not ... to be ... the ...

[Signature]
28.6.32



© 2020

Lloyd's Register Foundation
W12 56 9306