

N.B. - All alterations in the existing records should be made

2m.27. H.

16 - MAR 1934

Report to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel Sc. "ACHILLE LAURO" Report London No. 99801a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 21.5.32.)

1st No. 3 SURVEY PARTLY HELD.

When due 2,33 When proposed to be completed

Portion of Survey held, &c.,

The 1st S.S. No.3, due 2,33, has been partly held.

Repairs are required to the deck, casings, tank top under boilers and in way of leaky rivets in No.2 double bottom tank on starboard side, and the rudder mainpiece, repaired by electric welding 9,33, requires to be specially examined at the next dry docking.

The Naples Surveyor now forwards a letter from the Owner to the effect that in the interests of economy he has been compelled to withdraw this vessel from this Society's classification.

It is submitted the class of this vessel be withdrawn from the Register Book and three dots, (...), inserted in lieu, indicating withdrawal of class at the Owner's request.

Withdraw class
Insert ...

Handwritten initials

Handwritten signatures and date 8.3.34



© 2020

Lloyd's Register Foundation

W1258-0219

W1258-0222

Vertical text on the right edge of the page, including "Year Assigned expired", "Wood V", "Month", "rang", "ing Riga", "Book o", "and to".