

Rec'd
Sent to Chief Surveyors 5-4-34

Received from Chief Surveyors

VESSEL'S NAME M. S. PIONEER Report N. Y. K. No. 35799

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Ship Committee's Report 24/5/92.)

Nature of Survey Withdrawal of class. When due A. S. S. No. 3 held on hull (after an early No. 3)

Subject to the bottom plating in cargo tanks (from 1 to 7 inclusive) being specially examined & dealt with at the next drydocking & the indented shell plating forward starboard side being jaired at first convenient opportunity.

M. B.
[Signature]
10-4-34

PLATING to be DRILLED when vessel is 24 years old, or at next Special Survey thereafter.



© 2020

Lloyd's Register
Foundation

W1263-0172