

01265-0249

TMV. Teresa Oders.

Gen 9741.

It is submitted the Genoa Surveyors be requested forward the plan of this vessels boilers which is not appear to have been received at this Office. At the same time it is concluded that the sizes the main crank shaft webs given in their report is made in error but they should state if this

They should also state whether the screw shaft liner is in one length, or if more than one length, whether the joint is burned or soldered. JWD. 16/2/27.