

17- SEP 1933

Steel Screw Ketch "DAVID OGILVIE"  
-----

The class of the vessel was expunged with a red line last month on account of Boiler repairs not being carried out under survey.

In a letter dated the 15th ultimo acknowledging receipt of the letter in which the Committee's action was conveyed, the Owner stated that the vessel was withdrawn from class owing to the action of the Surveyor who did not attend when requested.

The matter has been submitted to the Surveyor for his remarks and in his reply he states that the Owners assertion is untrue and that he attended on board at 9.15 a.m. on the 18th ultimo after receiveing an intimation on the 17th at 4 p.m. that the Boiler was ready.

It is submitted the Surveyor's explanation is satisfactory and that no further action is necessary.

*My* *AL* *209*  
6. 9. 33.



© 2020

Lloyd's Register  
Foundation

W1266-0016