

29 MAR 1933 ^{3 E}

Received from Chief Engineer/Surveyor

Surveyor

B421

Rpt.

L.A.

No. 4571.

Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

ment to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points of the endorsement. — Extract from Sub-Committee's Report, 24/5/32.

SPECIAL SURVEY OF ~~ENGINES AND/OR~~ BOILERS PARTLY HELD ~~FOR 3 3 3~~

9.32, partly held

recommended

and the following repairs ~~effected~~ (due to wear & tear)

Boiler. Re-joint bottom row off valve on ~~then~~
 Cracked front & circumferential seam at
 bottom, Repair Centre furnace mouth,
 Repair Centre fire box plating where cracked &
 leaky.

proposed to complete the survey not stated.

The Engineer recommends that the repairs be effected without delay.

is submitted that this proposal merits approval and the vessel is

to remain as classed, and WILL BE eligible for the record

13 when the survey has been completed.

following remains to be done to complete the Survey

The above repairs to be effected.

Adv. Owners.

for survey due 1.33 to be held
 on docking. Approved



© 2020

29/3/33

Lloyd's Register
 Foundation