

10 OCT 1941

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME.....STYLIANOS CHANDRIS.....Rpt.....Cff.....No. 54013

Hfx

No. 3598

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to the forward end of the solepiece of sternframe, E.W. 6.39 and 4.40, being specially examined at the next dry docking.

The CARDIFF Surveyors report the vessel placed in dry dock, bottom coated, and a rudder pintle renewed.


Minor repairs effected.

The sternframe solepiece as above specially examined and found satisfactory.

The Halifax N.S. Surveyor reports the heating coils in deck tank blanked off on account of leakage & he recommends these be tested at the first opportunity
It is submitted the vessel appears worthy to remain as classed with record of survey 9.41, subject as above and as recommended.

100A1)
Shelter dk)
with fbd)
9.41 Cff) Subject etc.
Fitted for)
oil fuel)
etc.)

PLATING to be DRILLED when vessel is 24 years old, or at next Special Survey thereafter.



b7M © 2019

9-10-41

16-10-41

Ld. Ins. 13/10

Lloyd's Register Foundation

2200-72119