

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing girders, and of the inner bottom plating, especially in the boiler space.

Last Report No. 32720

CHARACTER.
* for Special Survey.
Date of last Survey and of
Periodical Surveys.

TELEPHONES { 0220
0221
0222
0223 } WHITEHALL-4

CABLEGRAMS: NYMDIBLE, NEW YORK.



Lloyd's Register of Shipping,

17 Battery Place,

New York.

May 19th, 1933.



"H"

Dear Sir:-

With reference to your letter of the 20th ultimo regarding the boilers of the Steamer "CABIMAS", I may say that the Owners inform me that steam has not been raised on these boilers, nor is it likely to be raised until she again goes into commission.

I am, Dear Sir,

Yours faithfully,

Sturges
Chief Surveyor,
U.S.A. & Canada.

The Secretary,

LONDON.



© 2020

Lloyd's Register
Foundation

W1270-0173

Travelling Expenses (if chargeable) £

19

Surveyor to Lloyd's Register

~~Referred to the Chief Ship Surveyor.~~
(Referred).

Referred to Mr. Spink.

C/S

27 MAY 1933

27 MAY 1933

27 MAY 1933

27 MAY 1933

the ship was into collision.

latter on these points. It is likely to be noted that

I may say that the cause of the accident was not seen

and this regarding the nature of the accident.

It is referred to the report of the

27 MAY 1933

27 MAY 1933

New York

12 BRUCE PLACE

12 BRUCE PLACE



© 2020

Lloyd's Register
Foundation

Last Page