



GENERAL REMARKS (State quality of workmanship, opinions as to class, &c.)

The materials used in construction of this boiler were tested by R.N.I. (see report on Rapallo - Gen Rpt No 8134)

The boiler was surveyed during construction and the materials and workmanship are good. It was tested as required by the Rules by hydraulic pressure, securely fitted aboard and also tried with satisfactory results under steam.

Port of

No. in Reg. Book

Owners

Yard No

DESCRIPTION

2 sets

steam

drum

Capacity

Where is

Position of

Positions

with 8

1 forw

If fuses

circu

If vessel

Are the f

Are all fu

are p

Are all su

Total num

A Inq

B Accom

C Saloon

D Pump

E Gas

ma

2

If arc ligh

Where are

DESCRIPTION

Main cables

Branch cab

Branch cab

Leads to lan

Cargo light

DESCRIPTION

Main

Lan

Joints in ca

Are all the j

position

Are there a

How are the

Certificate (if required) to be sent to  
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

The amount of Entry Fee .. £	See mach. repar.	When applied for,
Special .. .. . £		.....19.....
Donkey Boiler Fee .. .. £		When received,
Travelling Expenses (if any) £		.....19.....

Committee's Minute FRI. 23 MAR. 1913

Assigned

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping



© 2020 Lloyd's Register Foundation