

Hamburg Report Nr. 19226

5th March 1930

Surveyed the Boiler^s and Machinery of the Steel Twin Sc.

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all

recommendations made by me in connection therewith have

been carried out to my satisfaction, and that I have

Recommended that the record of IMC 3.30. Tail Shafts (OG)

seen 3.30. and + NB 3.30. xx

be made in the Register Book in the case of this vessel.

A. Carstensen

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for accuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

Lloyd's Register
Foundation

W1277-0060