


of "San Florentino."

It is submitted the Newcastle Surveyors should be informed that it is concluded a spare bucket rod for the lubricating pump has been placed on board but as no mention is made of it in their report they should state if this is so.

They should be requested to forward a diagrammatic sketch of the arrangement of the turbines, shafts & gearing & state whether the screw shaft is fitted with a continuous liner.



© 2019

27/5/19

Lloyd's Register
Foundation

W128-0117