

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report Sept. 4, 1935 When handed in at Local Office Sept. 4, 1935 Port of NEW YORK

No. in Reg. Book. 30186 Survey held at on the Wood, Iron or Steel S. S. "MONTANAN" Date, First Survey - - Last Survey - - (No. of Visits 19)

TONNAGE 1898 Built at Philadelphia, Pa. By whom W. Cramp & Sons S & E B Co. When 1917 4
GROSS 1898 Owners American Hawaiian S. S. Co. Owners' Address (if not already recorded in Appendix to Register Book).
UNDER DEK. 1353 Managers Port belonging to New York
NET 2866

Surveyed Afloat or in Dry Dock? WB=CellDBorDBa Name of Dock feet; uE&B Destined Voyage feet; f
total capacity tons. FPT tons; APT tons; MT feet tons. } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 3078 Port Ros.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned may expired.	Machinery and Boiler Surveys (including date of N.E., if any).
*100 A1 4,34		*LMC MS 8,33
Shelter deck with freeboard		BS 11,34 CL 7,32
SS Bos.No.3-8,29		
SS Bos.No.1-33		
Fitted for oil fuel above 150° F.		4,17 F.P.
Society's Freeboard (if assigned) as painted on Ship and now verified		ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

The Owners have requested that this vessel be withdrawn from classification with this Society (see letter from Owners dated August 27th, 1935).

133

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year
Caulking of Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	Boats
Coamings	Bulkheads	Engine Room Skylights	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Condition, how ascertained (State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Oil Bunkers	Sails
" " in way of sidelights	Rudder	Scuppers	Equipment letter
Breasthooks	Steering gear and its connections	Cargo Hatchways	Anchors, No. of
Transoms	Windlass	Hatches	Chain Locker
Frames	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Cables (State if now ranged)
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	" length mean diamr. (on board)
Longitudinals	Have Watertight Doors now been examined and found efficient?	Treenails ditto	" Rule length size
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	Hawser & Warps
Floors		Transoms Pointers, & Crutches ditto	Standing and Running Rigging
Keelsons		Timbers of Frame at openings? ditto	
Stringers		Ditto Ditto at other places ditto	
Inner Bottom Plating		Stringers, Clamps & Sheifs ditto	
		Salting ditto	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptnd24, &c."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19.
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19.

Committee's Minute

Character Assigned Withdraw class and insert...

French
Surveyor to Lloyd's Register of Shipping.
General Committee
Thursday, 19th September, 1935
Decision of Classing Register
Committee confirmed
Foundation