

REPORT of SURVEY for REPAIRS, &c.

UNCLASSIFIED
DAL 10-130

Date of writing Report 19... When held at Local Office 19... Port of London

No. in Reg. Book. 86492 Survey held at on the Wood Iron or Steel TONAN MARU Date, First Survey 1921 Last Survey 19

TONNAGE: GROSS 4240 Built at Imoshima By whom Osaka Iron Works When 1921 MONTH 5

UNDER DECK 3674 Owners Dairen Kisen K.K. Owners' Address (if not already recorded in Appendix to Register Book).

NET 2433 Managers Dairen Port belonging to Dairen

Surveyed Afloat or in Dry Dock? W=B=CellDBorDBa Name of Dock W=B=CellDBorDBa Destined Voyage W=B=CellDBorDBa

feet; uE&B feet; f feet; total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 6107 Port Sea

CHARACTER.	Years Assigned	Machinery and Boiler Surveys
For Special Survey	1	(including date of N.B., if any).
Date of last Survey and of Periodical Surveys.		
+ 100 A1		+ LMC 7.34
Below 100 with freeboard 7.34		Ch 7.34
SS Dm 10 3- 7.34		

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Paired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	State if Tanks now tested	Dble. Plates under Sounding Pipes	(State if on Felt).
Caulking of Decks	Bulkheads	Engine Room Skylights	When put on, Month Year
Coamings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Boats
Beams & Fastenings	Cement or Asphalt (State which.)	Oil Bunkers	Masts, Yards, &c.
Outside Plating	Rudder	Scuppers	Condition, how ascertained
" " in way of sidelights	Steering gear and its connections	Cargo Hatchways	(State if wedges removed)
Reasthooks	Windlass	Hatches	Sails
Transoms	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Equipment letter
Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	Anchors, No. of
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Treenails ditto	Chain Locker
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	Cables (State if now ranged)
Transverses		Transoms Pointers, & Crutches ditto	length mean diam.
Floors		Timbers of Frame at openings ditto	(on board)
Keelsons		Ditto Ditto at other places ditto	Rule length size
Stringers		Stringers, Clamps & Shelves ditto	Hawser & Warps
Inner Bottom Plating		Salting (State if examined.) ditto	Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and pEND24, &c."

Survey Fee (per Section 20)	£	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	19
Travelling Expenses (if chargeable)	£	Received by me,
Second Surveyor's Fee (if any)	£	19

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

TUE. 21 MAY 1935

General Committee

Thursday, 23rd May, 1935

Classing Committee's decision confirmed

W1283-0255