

Do. of R.
Do. of R.

by Chief Ship Surveyor 8/8/11

Received from Chief Ship Surveyor

EL'S NAME *At St. Holey*

Rpt. *Rur*

No. *60793*

he remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey *First entry*

It is submitted that before this case comes the consideration of the Committee the 1st entry report, together with the midship section & the section showing the intermediate bracket floors should be returned to the Newcastle Surveyors & they should be requested to state whether they are correct in their statement that the frames at the intermediate brackets are $8\frac{1}{2} \times 3\frac{1}{2} \times .40$ & not $8\frac{1}{2} \times 3\frac{1}{2} \times .45$ as shown on the plan. They should also state whether the thickness of the gun deck plating is .40 to .34 as reported or .34 as shown on the approved plans. If the former is the case they should amend the plans accordingly.

L. New 9/8/11
Report & 2 plans

M *RBA*
8/8/11
© 2020



Lloyd's Register
Foundation

W1288-0078