

13 MAY 1942

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME TIA JUANA

ARU
Rpt. San Nicholas No. 375

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The class is subject to indented shell plate
G.11 (s.s.) being permanently repaired at the Owners' convenience.

(1.42)

The SAN NICHOLAS ARUBA Surveyor reports the
vessel placed on a slipway and bottom coated.

The shell plating above turn of bilge (p.s.) in way
of after wing ballast found slightly indented, cause not stated.

The Surveyor makes no recommendations regarding
repairs to this plating.


The Pitting in the doubling plates in way of propeller
built up by electric welding.

It is submitted the vessel appears worthy to remain as
classed with record of docking survey 1.42 subject as above.

100A1

1.42 ~~San Nicholas~~ Ara.
Carrying petroleum in bulk
Fitted for oil fuel etc.

} Subject etc.



© 2019

Lloyd's Register
Foundation

W129-0181