

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report: 3rd Aug 1934 When handed in at Local Office: 3rd Aug 1934 Port of Call: Caliz.
No. in Reg. Book: 11184 Survey held at: Caliz.
Date, First Survey: 1 Last Survey: 3rd Aug 1934
(No. of Visits: 1)
TONNAGE: GROSS 291 Built at: Hull By whom: Garle's Co. Ltd When: 1909-4
UNDER DECK: 262 Owners: Enrioso Hummoe S.A. Owners' Address: (if not already recorded in Appendix to Register Book).
NET: 114 Managers: Port belonging to: Barcelona.

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock: Malagon, C. Destined Voyage:

U.B. = Cell D Bor D Ba. feet; u E & B feet; f feet
Capacity tons. FPT tons; APT tons; MT feet tons.

All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Report, No. 3084 Port Cal

ical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent repairs. Repairs account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the placement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

cases where the Surveyor has not made a special damage report he is required to state whether he has his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

OR EXAMINATION AS PER RULE, FOR Condition.

Notes: - Vessel placed in dry dock and bottom and hull examined, examined and coated.
Rudder raised & wood filling pieces replaced.
Steel plates fitted on top of wood deck in way of rudder.
Plating.

OF DAMAGE REPAIRS:—

	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
red								
red and Faired or Repaired								
red or Repaired in place								

CONDITION OF THE

Decks	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
Stenings	State if Tanks now tested	Dblng. Plates under Sounding Pipes	(State if on Felt).
ng	Bulkheads	Engine Room Skylights	When put on, Month
in way of sidelights	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Boats
	Cement or Asphalt	Oil Bunkers	Masts, Yards, &c.
	(State which.)	Scuppers	Condition, how ascertained
	Rudder	Cargo Hatchways	(State if wedges removed)
	Steering gear and its connections	Hatches	Sails
	Windlass	Planking of Wood Vessels	Equipment letter
nes	Have pumps now been examined and found efficient?	Caulking ditto	Anchors, No. of
	Have Sluice Valves now been examined and found efficient?	Treenails ditto	Chain Locker
	Have Watertight Doors now been examined and found efficient?	Breasthooks & Stemson ditto	Cables (State if now ranged)
	Have Ventilators and their Coamings been examined and found efficient?	Transoms Pointers, & Crutches ditto	length mean diamr.
		Timbers of Frame at openings ditto	(on board) size
		Ditto Ditto at other places ditto	Rule length
		Stringers, Clamps & Shells ditto	Hawser & Warps
		Salting ditto	Standing and Running Rigging
		(State if examined.)	

val Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

This vessel is eligible, in my opinion to remain as classed in fresh record of survey 8. 34 Cdy.

(per Section 20) Class 110.00:

age or Repair Fee (if any) £

Expenses (if chargeable) £

Surveyor's Fee (if any) £

Fees applied for,

3rd Aug 1934

Received by me,

19

mittee's Minute

TUE. 21 AUG 1934

Character Assigned

100A1

steam trawler

B.S. 8.34

Surveyor to Lloyd's Register of Shipping

WED 7 AUG 1935

Lloyd's Register

Foundation

W1297-0074

General Committee,
Thursday, 8th August, 1935.
Decision of Classing
Committee confirmed

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT.		WEIGHT OF STOCK.		TEST PER CERTIFICATE.		WEIGHT REQUIRED BY RULE.		Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Cwts.	qrs.			
	1st Bower ...											
	2nd "											
	3rd "											
	Collecting Weight.											
	Stream											
	Kedge.....											

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

Number of Certificate.	Length and size supplied.		Test per Certificate.		WEIGHT OF CHAIN CABLE.		Length and size per Rule.		Description.	Makers of Cables.	When and where tested and Superintendent.
	Length.	Diam.	Statutory.	Breaking.	Supplied.	Per Rule.	Length.	Diam.			
	Fathoms.	In.	Tons.	Tons.	Cwts. qrs. lbs.	Cwts. qrs. lbs.	Fathoms.	In.			
Iron Stream Chain or Steel Wire....											

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.